
Following NOTAM were still in force as of 2003020600utc.

Series A- International Distribution.

Year- 2019 - A0068, A0081, A0082.
2020 - A0004

Last Publications

AIRAC AIP Amendment: 01/20
AIP Amendment: 02/19
Supplements: S03/20
AIC: 07/19

NR	DATE	TEXT
----	------	------

2019

- A0068 1911251815/2003280305 REF AIP AD FSIA-1, section 2.3 (OPERATING HOURS) extension of runway closure due maintenance. Monday between 1815utc to Tuesday 0305utc until 28th March. The re-opening will return to 0245utc thereafter. Runway can be-opened within 30 minutes in cases of emergencies.
- A0081 1912310407/2003311200 Pilots and Operators of any Boeing 737-8 Max and Boeing 737-9 Max aircraft which are not registered in Seychelles or are registered in another foreign are not to conduct any flights as follows:
a) Aircraft registered in the Seychelles must not be flown anywhere.
b) Aircraft registered in a third country must not be flown in Seychelles Airspace/FIR.
- A0082 1912310428/2003311200 2NM array approach steady lights 13 unserviceable.

2020

2002270001/2003120001 TRIGGER NOTAM - PERM AIRAC AIP AMDT 01/20 With effective date 27 February 2020. Editorial changes.